



S.E. WINGWALL (Looking West)

SOUTH ABUTMENT (Looking South)

S.W. WINGWALL (Looking East)

## BILL OF MATERIAL

Item	Unit	Total							
Structural Repair of Concrete (Depth Equal to or less than 5")	Sq. Ft.	654							

Notes: Hatched area indicates approximate area of Structural Repair of Concrete. Exact repairs are to be determined by the Engineer.

All existing abutment seats shall be cleaned & sealed. Work will be paid for as Cleaning Bridge Seats.

Allen Henderson & Associates, Inc. Civil and Structural Engineers Springfield, IL. 62703 Phone: (217)544–8033 IL. Design Firm No. 184-001907

SHEET NO.12 14 SHEETS

					TE I	160	CRETE REPA D OVER U.S. N. 014-0065			
F.A.P. RTE.	SECTION					COUNTY	TOTAL SHEETS		SHEET NO.	
690 14-12BR-1					CLINTON	72		32		
					CONTRACT	NO.	76	B27		
 FED. RO	DAD DI	ST.	NO	ILLINOIS	FED.	ΑI	D PROJECT			